

<b>L Number</b>	<b>Hits</b>	<b>Search Text</b>	<b>DB</b>	<b>Time stamp</b>
<b>12</b>	<b>80</b>	<b>(TSUBOI near1 MASA HARU).in.</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB</b>	<b>2002/02/22 17:06</b>
-	<b>108</b>	<b>control adj board and (motor same vehicle same electric)</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB</b>	<b>2002/02/22 17:05</b>
-	<b>15681</b>	<b>electric adj vehicle</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB</b>	<b>2002/02/21 20:14</b>
-	<b>84</b>	<b>(electric adj vehicle) and board same (casing or housing)</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB</b>	<b>2002/02/21 20:15</b>
-	<b>11</b>	<b>("4259603"   "4633110"   "4668898"   "4673834"   "4724347"   "5049769"   "5663604"   "5691584"   "5705868"   "5841208"   "5895994").PN.</b>	<b>USPAT</b>	<b>2002/02/22 11:25</b>
-	<b>1935</b>	<b>310/91</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 10:38</b>
-	<b>8</b>	<b>310/91 and ((pcb or (circuit adj board)) same rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 10:58</b>
-	<b>117</b>	<b>shaft same ((pcb or (circuit adj board)) same rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 10:54</b>
-	<b>1016</b>	<b>(310/68r).CCLS.</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 10:54</b>
-	<b>1</b>	<b>((310/68r).CCLS.) and ((pcb or (circuit adj board)) same rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 10:55</b>
-	<b>3</b>	<b>310/91 and ((pcb or (circuit adj board)) same grommet)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 11:07</b>
-	<b>10</b>	<b>310/91 and ((pcb or (circuit adj board)) same sleeve)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 11:07</b>
-	<b>1584</b>	<b>(310/90).CCLS.</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 11:25</b>
-	<b>112</b>	<b>((310/90).CCLS.) and sleeve adj bearing</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 11:26</b>
-	<b>3</b>	<b>((310/90).CCLS.) and ((sleeve adj bearing) same rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 12:12</b>
-	<b>6</b>	<b>("3644066"   "4373861"   "4564335"   "4612468"   "4737673"   "4783608").PN.</b>	<b>USPAT</b>	<b>2002/02/22 11:41</b>
-	<b>16</b>	<b>4955791.URPN.</b>	<b>USPAT</b>	<b>2002/02/22 11:44</b>
-	<b>7</b>	<b>310/\$.ccls. and ((sleeve adj bearing) same rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 12:14</b>
-	<b>20</b>	<b>310/\$.ccls. and ((circuit adj board) WITH rubber)</b>	<b>USPAT; US-PGPUB</b>	<b>2002/02/22 12:28</b>

-	35	electric adj motor and ((circuit adj board) WITH rubber)	USPAT; US-PGPUB	2002/02/22 12:53
-	153	(310/dig.6).CCLS.	USPAT; US-PGPUB	2002/02/22 12:32
-	9	((310/dig.6).CCLS.) and rubber	USPAT; US-PGPUB	2002/02/22 12:32
-	1194	((circuit adj board) WITH rubber)	USPAT; US-PGPUB	2002/02/22 12:40
-	33	((circuit adj board) WITH rubber)) and rotor	USPAT; US-PGPUB	2002/02/22 12:51
-	5	("1688891"   "2301425"   "3330515"   "3459977"   "3527969").PN.	USPAT	2002/02/22 12:46
-	5	5444314.URPN.	USPAT	2002/02/22 12:49
-	2	jp-59050750-\$.did.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 12:52
-	1	electric adj motor and ((circuit adj board) WITH rubber)	EPO; JPO	2002/02/22 12:54
-	540	((circuit adj board) WITH rubber)	EPO; JPO	2002/02/22 12:55
-	2	( ((circuit adj board) WITH rubber)) and stator	EPO; JPO	2002/02/22 12:57
-	4	( ((circuit adj board) WITH rubber)) and rotor	EPO; JPO	2002/02/22 12:59
-	151	( ((circuit adj board) WITH rubber)) and electric	EPO; JPO	2002/02/22 12:59
-	1	( ((circuit adj board) WITH rubber)) and electric adj motor	EPO; JPO	2002/02/22 13:00
-	1	( ((circuit adj board) WITH rubber)) and winding	EPO; JPO	2002/02/22 13:02
-	3	( ((circuit adj board) WITH rubber)) and magnet	EPO; JPO	2002/02/22 13:03
-	38	310/91 and rubber and (circuit adj board)	USPAT; US-PGPUB	2002/02/22 13:04
-	1	wo-9733359-\$.did.	EPO; JPO	2002/02/22 16:52
-	1115	(310/91).CCLS.	USPAT; US-PGPUB	2002/02/22 16:53
-	1016	(310/68r).CCLS.	USPAT; US-PGPUB	2002/02/22 16:54
-	153	(310/dig.6).CCLS.	USPAT; US-PGPUB	2002/02/22 16:54
-	806	(310/64).CCLS.	USPAT; US-PGPUB	2002/02/22 16:56
-	826	(310/51).CCLS.	USPAT; US-PGPUB	2002/02/22 16:59
-	293	H02K005/24.ipc.	USPAT; US-PGPUB	2002/02/22 17:00
-	3259	H02K005/24.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:00

-	9099	H02K011/00.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:01
-	2416	H02K005/00.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:02
-	718	H02K005/18.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:02